

FIG.1

[ROLLING BEARING UNDER TEST]

OCCURRENCE OF INDENTATIONS DUE
TO WEAR PARTICLE PENETRATION

LUBRICANT DEGRADATION

DATA ACQUISITION FOR EACH
BEARING SPECIFICATION



[DIAGNOSTIC ROLLING BEARING]




FIG.2




FIG.3




FIG.4




FIG.5




FIG.6




FIG.7




FIG.8




FIG.9




FIG.10




FIG.11




FIG.12

